



Lead Service Line Inventory

Water System Name		CITY OF VIRDEN WATER DEPT			System ID Number:		IL1171100		Current Inventory Date:		4/10/2024	
Total Service lines:		1732	Total Lead:	0	Total Non-Lead:	1732	Total Galvanized Requiring replacement:	0	Total Unknown:	0	Website link to Material Inventory:	WWW.VIRDEN.MUNICIPALIMPACT.COM

Lead Service Line Inventory

Water System Name:	CITY OF VIRDEN WATER DEPT.	System ID Number:	IL1171100	Current Inventory Date:	04/10/2023	Previous Inventory Date:	04/15/2022	Has Funding Assistance Been Requested?:	NO
--------------------	----------------------------	-------------------	-----------	-------------------------	------------	--------------------------	------------	---	----

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?
603 N SPRINGFIELD	N/A	Y	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
123 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
131 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
618 N NOBLE	NA	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
622 N NOBLE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
628 N NOBLE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
634 N NOBLE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 W VANCE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
706 N NOBLE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
710 N NOBLE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
720 N NOBLE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
205 W UNION	LP3S029	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
209 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
215 W UNION	LP3S030	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
305 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
315 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
321 W UNION	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
333 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
821 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
231 W UNION	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
822 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
318 W LINCOLN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
336 W LINCOLN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
335 W LINCOLN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
311 W LINCOLN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
905 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
730 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
912 N GROVE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
920 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
928 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
925 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
933 N GROVE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
941 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
940 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
946 N GROVE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N

255 OLIVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
303 OLIVE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
307 OLIVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
317 OLIVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
323 OLIVE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
231 OLIVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
248 E OLIVE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
238 E OLIVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
231 OLIVE ST	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
214 OLIVE ST	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
144 OLIVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
152 OLIVE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1317 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
204 E OLIVE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1350 N DYE	LP3S004	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1320 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
153 PINE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
140 E PINE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
143 PINE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
133 PINE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
123 E PINE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1304 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1324 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1210 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1204 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1122 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
1130 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
110 E SPRUCE ST	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
130 SPRUCE ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
144 E SPRUCE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
146 E SPRUCE ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
144 LIBERTY CRT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
161 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
131 SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 LIBERTY CRT	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
118 LIBERTY CRT	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 LIBERTY CRT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
111 LIBERTY CRT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
114 LIBERTY CRT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1040 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
1104 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1705 SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
318 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
330 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
113 E WAVERLY	LP3S032	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
422 N SPRINGFIELD ST	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
428 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
434 N SPRINGFIELD ST	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 E HILL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
122 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
536 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
112 E FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 E FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 E FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
130 E FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
132 E FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
611 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
613 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
615 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
617 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
619 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
621 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N

623 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
625 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
626 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
627 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
629 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
633 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
631 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
635 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
637 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
639 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
641 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
512 N DYE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
131 E FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
125 E FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
121 E FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
105 E FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
618 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
630 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
634 N SPRINGFIELD ST.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
122 E VANCE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
126 E VANCE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
156 E VANCE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
188 E VANCE ST.	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
177 E VANCE	LP1A038	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
155 E VANCE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
133 E VANCE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
722 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
130 E UNION	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
134 E UNION	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
138 E UNION	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
150 E UNION	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
703 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
141 E UNION	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
137 E UNION	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
707 W LINCOLN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
820 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
826 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
122 E LINCOLN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
126 E LINCOLN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
136 E LINCOLN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
730 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
152 E LINCOLN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
223 E LINCOLN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
231 E LINCOLN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
236 STODDARD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
245 LINCOLN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
203 E LINCOLN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
145 E LINCOLN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
141 E LINCOLN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
600 E WINEMAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C		NL	N	N/R	N	N/R	N/R	N
600 E WINEMAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
129 E LINCOLN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 E LINCOLN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
910 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
916 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
920 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
928 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
731 E JACKSON ST	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
124 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
130 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N

134 STODDARD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
142 E STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
150 STODDARD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
920 N DYE ST	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
605 LYNNE ST	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
210 STODDARD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
220 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
232 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
236 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
242 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
252 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
231 E STODDARD AVE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
223 STODDARD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
221 E STODDARD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
209 STODDARD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
203 STODDARD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
141 STODDARD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
139 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
135 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
125 STODDARD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 E STODDARD ST.	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1000 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1020 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1024 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C		NL	N	N/R	N	N/R	N/R	N
309 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
315 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
323 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
327 N DYE ST.	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
333 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
122 E WAVERLY	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
403 N DYE	LP3S002	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
409 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
413 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
421 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
429 N DYE	LP3S003	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
435 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
125 E HILL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
129 E HILL	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
505 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
513 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
519 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
525 N DYE ST.	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
518 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
520 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
516 SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
522 SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
945 N GROVE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
206 MALTBY ROW	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
225 MALTBY ROW	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
231 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
525 N MASTERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
232 E HILL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	c	NL	N	N/R	N	N/R	N/R	N
222 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
223 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
434 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
420 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
414 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
408 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
207 E WAVERLY	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
233 E WAVERLY	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
415 N MASTERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
409 N MASTERSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N

231 OLIVE ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
234 E WAVERLY	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
332 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
326 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
322 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
316 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
310 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
304 N DYE ST	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
301 N MASTERSON	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
309 N MASTERSON	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
317 N MASTERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
319 N MASTERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
315 N MASTERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
971 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1128 N GROVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
15 BRADEN CT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
14 BRADEN CT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
420 CEMETERY RD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
7 BRADEN CT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
217 W SPRUCE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
211 MEADOWLARK	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
114 W WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1105 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
18477 TIMBER LN.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1416 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1330 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
138 STELLE ST	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
136 STELLE CT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
134 STELLE CT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
132 STELLE CT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
130 STELLE CT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
128 STELLE CT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 STELLE CT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
124 STELLE CT	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
122 STELLE CT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 STELLE CT	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1240 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1230 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
129 E SPRUCE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
135 E SPRUCE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1201 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1203 N DYE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
226 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
524 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
144 E VANCE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
740 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
210 MALTBY ROW	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
128 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
130 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
206 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
216 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
220 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
224 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
232 S SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
221 S WRIGHTSMAN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
221 S WRIGHTSMAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
311 S SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
319 S SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
327 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
115 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
117 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
403 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
409 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N

205 W HILL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
209 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
215 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
222 W HILL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
221 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
231 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
510 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
240 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
208 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
204 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
132 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
130 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
373 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
379 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
379.5 W HILL ST	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
381 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
540 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
546 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
604 CAREY APT A	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
604 CAREY APT B	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
605 N CAREY	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
613 CAREY	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
324 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
359 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
414 W HILL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
349 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
345 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
341 W HILL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
329 W HILL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
323 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
315 W HILL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
305 W HILL	LP1A040	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
433 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
430 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
425 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
413 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
410 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
409 N BLAIR	LA3S041	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
403 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	PVC	NL	N	N/R	N	N/R	N/R	N
231 W WAVERLY	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
227 W WAVERLY	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
221 W WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
220 W WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
334 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
326 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
322 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	PVC	NL	N	N/R	N	N/R	N/R	N
316 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
227 W PRAIRIE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	PVC	NL	N	N/R	N	N/R	N/R	N
	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
223 W PRAIRIE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
415 W WAVERLY	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
403 N FINIS APT B	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
331 W WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
325 W WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
425 N FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
460 N FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
328 W HILL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	PVC	NL	N	N/R	N	N/R	N/R	N
404 W HILL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
157 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
805 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
807 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
802 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N

804 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
830 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
601 EMMERSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
900 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
855 W FORTUNE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
650 EMMERSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
660 EMMERSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
695 EMMERSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
928 W UNION	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
820 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
901 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
621 CAREY	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
402 E JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
110 N BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
322 E DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
104 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
117 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
123 S BISSELL	LP3S014	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
106 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
128 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
415 E GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
418 E GREEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
412 E GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
404 E GREEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
222 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
414 E HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
302 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
340 E HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
327 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
324 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
332 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
336 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
331 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
339 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
343 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
345 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
365 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
353 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
360 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
370 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
381 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
383 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
404 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
408 S BISSELL	LP3S015	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
488 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
494 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
487 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
491 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
535 S EMMETT # 1	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
535 S EMMETT # 8	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	PVC	NL	N	N/R	N	N/R	N/R	N
528 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
527 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	PVC	NL	N	N/R	N	N/R	N/R	N
520 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	PVC	NL	N	N/R	N	N/R	N/R	N
502 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
444 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
352 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
520 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
231 OLIVE ST	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
348 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
329 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
332 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
318 S EMMETT	LP3S013	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
327 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N

504 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
450 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
520 E HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
438 E HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
235 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
333 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
229 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
223 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
215 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
523 E GREEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
323 S HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
538 E HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
560 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
607 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
611 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
701 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
703 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
603 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
320 S RING	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
323 S RING	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
317 S RING	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
315 S RING	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
610 LYNNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	PVC	NL	N	N/R	N	N/R	N/R	N
700 LYNNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
313 EARL	LP3S025	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
310 EARL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
309 EARL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
305 EARL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
704 LYNNE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
705 LYNNE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
701 LYNNE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
215 S RING	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
609 LYNNE	LP3S024	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
605 LYNNE	LP3S023	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
606 LYNNE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
601 LYNNE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
134 S HENDERSON	LP3S005	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
130 S HENDERSON	LA3S043	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
535 E GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
115 S HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
109 S HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 S HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
530 S DYE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
103 S HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
103 S HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
104 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
104 S HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
111 S. RING ST.	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
117 S RING	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
123 S RING	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
129 S RING	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 S RING	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 S RING	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
110 S RING	LP3S012	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
104 S RING	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
713 E DEAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
715 E DEAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
107 N RING	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
201 S IRIS	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
201 S IRIS	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
201 S IRIS	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N

121 N RING	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
712 E JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
722 E JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
731 E JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
630 E JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
235 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
206 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
136 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
524 S DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
518 S DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
506 S DYE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
208 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
527 E JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
110 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
117 N HENDERSON	LP1A036	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
123 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
528 E JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
502 S MASTERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
506 S DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
527 E JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
521 E JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
524 E JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
520 E JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
500 E JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1204 N SPRINGFIELD ST.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
112 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
104 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
118 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
128 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
138 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
155 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
115 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
109 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
103 S EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C		NL	N	N/R	N	N/R	N/R	N
109 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
125 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
133 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
423 E JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
429 E JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
204 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
500 S DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
427 E JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
221 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
224 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
210 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
216 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
227 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
233 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
240 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
233 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
501 E PRAIRIE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
523 E PRAIRIE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
522 E PRAIRIE	LP3S006	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
233 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
229 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
RIMINI	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N

533 E PRAIRIE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
319 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
329 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
333 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
531 E WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
340 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
421 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
429 N HENDERSON	LP1A037	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
433 N HENDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
432 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
428 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
424 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
448 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
444 N EMMETT ST	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
426 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
448 S. FIFTH ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
417 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
421 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
422 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
416 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
402 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
405 N. EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
410 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
424 E WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
425 E WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
432 E WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
332 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
328 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
322 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
323 N EMMETT	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
411 E PRAIRIE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
403 E. PRAIRIE ST.	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
322 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
326 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
330 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
416 N BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
410 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
426 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
429 E HILL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
427 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
405 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
339 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
323 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
230 N BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
104 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
106 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
108 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
110 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
112 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
114 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
118 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
115 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
113 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
111 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
109 BOB-O-LINK	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
107 BOB O LINK	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
105 BOB-O-LINK	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1516 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
1520 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
1524 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1525 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
1528 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1536 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N

1600 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1620 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1621 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1640 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1630 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
3 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
7 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
5 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
6 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
8 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
10 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
14 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
15 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
16 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
17 COUNTRY PL	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
19 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
20 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
110 CO LINE RD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
310 CO LINE RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
18993 STE RT 4	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
18700 STE RT 4	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
18718 STE RT 4	N/A	Y	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
108 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
112 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
144 ILLINI TRAIL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
156 ILLINI TRAIL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
20915 W MONTGOMERY RD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
211 CO LINE RD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
207 CO LINE RD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
417 W UNION	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
409 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
403 W UNION	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
803 COUNTRY VIEW	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
807 COUNTRY VIEW	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
808 COUNTRY VIEW	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
810 COUNTRY VIEW	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
405 KELLER	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
408 KELLER	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
412 KELLER	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
416 KELLER	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
417 KELLER AVE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
409 KELLER	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
413 KELLER	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
E 2 GASLITE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
C 6 GASLITE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
B 5 GASLITE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
936 JONES	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
930 JONES	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
920 JONES	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
910 JONES	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
906 JONES	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
914 JONES	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
204 HENRIETTA	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
955 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
438 S DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
430 S DYE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
814 JONES	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
822 JONES	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
852 JONES	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
21760 THOMASVILLE RD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
21691 THOMASVILLE RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
650 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
18839 PERRY	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N

6750 ILLINI DRIVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
6740 ILLINI DR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
6745 ILLINI DR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
6755 ILLINI DRIVE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	PO	NL	N	N/R	N	N/R	N/R	N
18925 PERRY DRIVE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6708 LORTON LANE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6710 LORTON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6720 LORTON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
420 S DYE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6730 LORTON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
6735 LORTON LANE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
LOT #54	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
6725 LORTON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6715 LORTON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
6709 LORTON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
6705 LORTON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
18865 PERRY	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6704 BECKER DRIVE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
6708 BECKER	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6712 BECKER DR	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6714 BECKER	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6711 BECKER	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6707 BECKER	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6676 TOWER HEIGHTS RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6716 TOWER HTS RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
6760 TOWER HTS RD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
6800 TOWER HTS RD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
203 E LOUD ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
228 E HOLDEN APT B	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
604 CAREY	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
340 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
334 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
450 W HILL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
305 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
303 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
545 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
307 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
309 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
301 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
403 N FINIS A	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
403 N FINIS C	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
157 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
330 LINDY LN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
920 W UNION	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
922 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
910 W UNION	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
926 W UNION	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
619 CAREY	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
122 S BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
301 E GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
231 S BISSELL ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
411 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
415 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
385 S BISSELL	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
535 S EMMETT #3	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
535 S EMMETT #5	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
535 S EMMETT #7	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
535 S EMMETT #6	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
535 S EMMETT #4	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
535 S EMMETT #2	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
521 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
523 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
525 S EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
801 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N

800 LYNNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
707 LYNNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
600 LYNNE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
124 N RING	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
124 N EMMETT APT B	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
515 E DEAN APT A	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
515 E DEAN APT B	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
515 E DEAN APT C	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
517 E DEAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
518 E DEAN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
501 E GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
224 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
690 RIMINI	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
520 E WAVERLY	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
320 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
440 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
420 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
430 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
416 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
418 N HENDERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
520 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
425 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
415 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
429 E HILL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
215 MEADOW LARK	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
251 E OLIVE ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
211 MEADOW LARK	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
110 MEADOWLARK	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 E MEADOWLARK LANE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
11 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
12 CO PLACE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
305 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
311 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
13 COUNTRY PLACE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
310 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
300 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
18 COUNTRY PL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
101 CO LINE RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
100 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
18718 STE RT 4	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
124 POST ROAD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
128 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
132 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
136 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
149 POST ROAD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
144 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
148 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
145 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
153 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
156 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
157 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
140 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
152 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 POST RD # 1	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 POST RD # 2	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 POST RD # 3	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 POST RD # 4	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
143 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
133 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
125 POST RD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
148 ILLINI TRAIL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N

152 ILLINI TRAIL	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
145 ILLINI TRAIL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
140 ILLINI TRAIL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
149 ILLINI TRAIL	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
219 CO LINE RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
215 CO LINE RD.	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
207 CO LINE ROAD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
926 JONES	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
123 N HENRIETTA	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 HENRIETTA	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
125 N HENRIETTA	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
816 JONES	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
818 JONES	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
21948 THOMASVILLE RD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
115 N CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 N CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
125 N CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
133 N CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
222 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
217 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
221 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
225 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
228 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
234 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
127 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
220 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
233 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
227 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
221 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
211 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
209 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
207 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
205 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
203 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
133 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
309 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
320 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
313 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
325 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
324 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
330 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
336 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
128 N FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
333 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
222 N FINIS	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
223 N FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
226 N FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
234 N FINIS	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
203 N FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
423 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
422 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
434 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
127 N HOBSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
131 N HOBSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
135 N HOBSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
139 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
151 N HOBSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
203 N HOBSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
232 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
523 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
533 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N

206 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
214 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
222 S BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
221 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
213 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
203 S BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
320 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
133 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
325 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 S FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
331 W GREEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 S FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
129 S FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
203 S FINIS	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
420 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
209 S FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
216 S FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
322 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
326 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
332 W GREEN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
422 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
423 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
429 W GREEN	LP3S027	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
432 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
216 S HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
542 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
133 S HOBSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
513 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
521 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
531 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
537 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
539 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
221 S WRIGHTSMAN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
227 S WRIGHTSMAN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
550 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
540 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
536 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
530 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
528 W GREEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
524 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
205 S HOBSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
431 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
225 S HOBSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
226 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
224 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
222 N BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
535 W HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
539 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
541 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
222 S WRIGHTSMAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
545 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
302 S WRIGHTSMAN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
540 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
528 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
526 W HOLDEN ST	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
524 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
232 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
230 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
232 N BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
230 W PRAIRIE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
222 W PRAIRIE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
305 S HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
333 S HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
525 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N

529 W LOUD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
533 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
555 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
316 S HOBSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
430 W HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
220 W PRAIRIE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
423 W HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
415 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
221 S FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
303 S FINIS	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
309 S FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
315 S FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
331 S FINIS	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
419 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
423 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
334 S HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
440 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
502 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
401 S WRIGHTSMAN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
111 SUNSET	LP35007	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 SUNSET	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
127 SUNSET	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
557 MEADOW	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
561 MEADOW	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
572 MEADOW	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
568 MEADOW	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
562 MEADOW	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
558 MEADOW	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
569 MEADOW LN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
575 MEADOW	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
595 MEADOW LN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
203 SUNSET	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
209 SUNSET	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
285 SUNSET	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
520 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
524 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
515 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
517 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
519 W WRIGHT	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
521 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
506 W WRIGHT ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
520 S WRIGHTSMAN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
500 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
496 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
285 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
486 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
280 MELODY LANE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
290 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
305 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
309 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
311 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
315 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
314 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
310 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
306 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
302 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
302 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
209 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
255 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
254 MELODY	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 SUNSET	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
204 SUNSET	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
210 SUNSET DR	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
110 SUNSET DR	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N

102 SUNSET DR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
406 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
331 W LOUD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
322 S FINIS	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
330 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
331 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
323 W HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
233 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
227 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
228 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
232 S BLAIR STREET	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
220 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
226 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
304 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
310 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
316 S BLAIR ST.	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
322 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
245 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
303 S BLAIR	LP3S034	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
311 S BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
319 S BLAIR	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
329 S BLAIR	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
325 W LOUD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
330 W LOUD	LP3S031	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
314 W LOUD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
302 W LOUD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
232 W LOUD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
222 W LOUD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
214 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
208 W LOUD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
211 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
205 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
327 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
204 W LOUD ST	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
419 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
425 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
431 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
437 S CHURCH	LP3S018	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
443 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
453 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
517 S CHURCH	LP3S019	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
521 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
527 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
533 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
537 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
547 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
601 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
550 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
544 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
540 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
534 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
528 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
522 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
514 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
508 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
120 W WRIGHT	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
502 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
454 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
442 S CHURH	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
434 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
426 S CHURCH	LP3S017	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
422 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
414 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
410 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N

404 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 W LOUD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
322 S CHURCH ST	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
324 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 W HOLDEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
236 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
226 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
216 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
134 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
131 W GREEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
128 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
122 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
123 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
124 N CHURCH -A	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 N CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
129 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
110 N CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
111 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
123 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
129 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
135 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
203 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
211 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
225 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
235 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
215 W HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
303 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	G	NL	N	N/R	N	N/R	N/R	N
315 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
321 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
233 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
229 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
223 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
215 S SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
215.5 S SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
209 S SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
203 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 W GREEN	LP3S026	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 W GREEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
119 W GREEN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
133 S SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
129 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
121 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
115 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
116 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
167 N LINDER	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
905 BRONAUGH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
715 JONES	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
										NL						
717 JONES	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
355 LINDER	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
835 W JACKSON ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
										NL						
850 W JACKSON #3	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
903 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	G	NL	N	N/R	N	N/R	N/R	N
909 W. JACKSON ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
929 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
950 BROADWAY	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
475 LINDER	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
905 JONES	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
859 JONES	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N

530 HENRIETTA	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
925 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
501 LINDER	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
854 SODA	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
256 N CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
300 N CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
316 N CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
261 N CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
247 N CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
237 N CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
248 CRANE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
232 N CRANE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
249 MOUSER	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
127 N CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
125 N CRANE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
130 N CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1055 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1103 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
1109 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
935 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	G	NL	N	N/R	N	N/R	N/R	N
231 CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
229 N CRANE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
905 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
815 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
21854 THOMASVILLE ROAD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
324 W PRAIRIE	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
105 SHORT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
701 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
705 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
640 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
630 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
700 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
710 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
730 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
720 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
740 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
620 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
610 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
608 W DEAN #1	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
608 W DEAN #2	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
604 W DEAN #1	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
604 W DEAN #2	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
600 W DEAN #1	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
600 W DEAN #2	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
101 S WRIGHTSMAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
103 S WRIGHTSMAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
105 S WRIGHTSMAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
107 S WRIGHTSMAN	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
112 N FINIS	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
306 S WRIGHTSMAN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
530 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
499 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
302 W WRIGHT - HYDRANT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
209 W LOUD	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
302 W WRIGHT	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
600 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
118 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
124 N CHURCH - B	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
124 N CHURCH - C	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
124 N CHURCH - D	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
113 S CHURCH	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
850 W BRONAUGH #1	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
850 W BRONAUGH #2	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N

940 W BRONAUGH #1	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
940 W BRONAUGH #3	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
940 W BRONAUGH #4	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
940 W BRONAUGH #5	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
911 W BRONAUGH	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
245 LINDER	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
										NL						
849 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
897 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
899 W JACKSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
920 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
929 W FORTUNE ST.	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
800 SODA	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
311 CRANE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
242 N CRANE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1100 W DEAN	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1269 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	P	NL	N	N/R	N	N/R	N/R	N
252 CRANE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
402 W LOUD ST	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
333 S WRIGHTSMAN	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
617 S SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
671 S CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
613 S SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
625 S SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
630 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
634 S SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
700 S SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
111 E PRAIRIE #1	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
109 E PRAIRIE #2	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
304 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
113 E PRAIRIE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
115 E PRAIRIE	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
314 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
N PLANT	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
SHOP	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
E PUMP	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
E PLANT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1515 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
755 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
231 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	P	NL	N	N/R	N	N/R	N/R	N
FINIS & PRAIRIE	N/A	N	Y	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
300 S SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
DRINKING FTN W PARK	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
S METER W SIDE OF	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
142 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
253 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
S METER W OF	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
N METER BETWEEN	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
139 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
521 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
217 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
211 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
101 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
169 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
130 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
161 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
159 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
157 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
155 N SPRINGFIELD ST	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
114 W JACKSON #3	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
112 W JACKSON #2	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
120 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
110 W JACKSON #1	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N

760 ANDERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
760 ANDERSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
760 ANDERSON	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
760 ANDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
760 ANDERSON	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
832 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
1046 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	P	NL	N	N/R	N	N/R	N/R	N
1525 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
1515 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
231 W FORTUNE	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
317 N SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
253.5 N DYE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
305 N DYE ST	LP3S001	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
542 W DEAN	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N SPRINGFIELD APT 5	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N SPRINGFIELD APT 6	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N SPRINGFIELD APT 7	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N SPRINGFIELD APT 8	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N SPRINGFIELD LAUDRY	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N SPRINGFIELD APT 1	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N SPRINGFIELD APT 2	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N SPRINGFIELD APT 3	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N SPRINGFIELD APT 4	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
151.5 N. SPRINGFIELD	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
118 W JACKSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
224 W CENTER ST	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
126 N HOBSON	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
224 N EMMETT ST	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
224 N EMMETT	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
146 N DYE ST	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
200 N BISSELL	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
125.5 E JACKSON #2	N/A	N	N	UNKNOWN	UNKNOWN	TELECOMMUNICATION	C	C	C	NL	N	N/R	N	N/R	N/R	N
115 CEMETERY RD	N/A	N	Y	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
127 W PRAIRIE	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
129 W PRAIRIE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
131 W PRAIRIE	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
304 N CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
306 N CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
308 N CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
310 N CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
312 N CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
314 N CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N/R	N/R	N
316 N CHURCH	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
167.5 N SPRINGFIELD	N/A	N	Y	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N
435 E HOLDEN	N/A	N	N	UNKNOWN	UNKNOWN	SURVEY RESPONSE	C	C	C	NL	N	N/R	N	N/R	N/R	N