



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name	Village of Davis	System ID Number:	IL1770150	Current Inventory Date:	8/29/2024						
*Please enter totals in the empty box next to each category	Total Service lines:	288	Total Lead:	18	Total Non-Lead:	233	Total Galvanized Requiring replacement:	36	Total Unknown:	1	Website link to Material Inventory:	https://villageofdavis.com/

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification			Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
		EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
120 N Turner St	19	N	Y	1930	1930	Survey Response	C	C	G	GRR	Y						
128 Stony Knoll		N	Y	1997	1997	Survey Response	G	G	G	GRR	Y						
308 N Blackmore		N	Y	1900	1900	Survey Response	G	G	G	GRR	Y						
311 N Beman		N	Y	1899	1899	Survey Response	G	G	G	GRR	Y						
318 N Beman St		N	Y	Late 1950s	Late 1950s	Survey Response	G	G	G	GRR	Y						
319 Stanton		N	Y	1845	1845	Survey Response	G	G	G	GRR	Y						
408 N Turner		N	Y	1952	1952	Survey Response	G	G	G	GRR	Y						
411 N Salisbury		N	Y	Unknown	Unknown	Survey Response	G	G	G	GRR	Y						
412 N Lee		N	Y	1900	1900	Survey Response	G	G	G	GRR	Y						
511 E Snyder		N	Y	1927	1927	Survey Response	G	G	G	GRR	Y						
607 Eply St		N	Y	1922	1922	Survey Response	G	G	G	GRR	Y						
608 N Davis		N	Y	1961	1961	Survey Response	G	G	G	GRR	Y						
612 E Snyder St		N	Y	1950	1950	Survey Response	G	G	G	GRR	Y						
620 N Blackmore		N	Y	1890	1890	Survey Response	G	G	G	GRR	Y						
711 N Turner St		N	Y	1921	1921	Survey Response	G	G	G	GRR	Y						
719 N Turner St		N	Y	1954	1954	Survey Response	G	G	G	GRR	Y						
804 IL Rt 75 East		N	Y	Late 1800s	Late 1800s	Survey Response	G	G	G	GRR	Y						
404 N Turner St		N	Y	1940s	1940s	Survey Response	G	G	G	GRR	Y						
127 Stony Knoll		N	Y	1997	1997	Survey Response	G	G	G	GRR	Y						
305 N Lee		N	Y	1970	1970	Survey Response	G	G	G	GRR	Y						
309 N Blackmore		N	Y	1950	1950	Survey Response	G	G	G	GRR	Y						
311 Snyder		N	Y	1890	1890	Survey Response	G	G	G	GRR	Y						
318 N Turner St		N	Y	1912	1912	Survey Response	G	G	G	GRR	Y						
320 Blackmore St		N	Y	1959	1959	Survey Response	G	G	G	GRR	Y						
411 N Lee		N	Y	1880	1880	Survey Response	G	G	G	GRR	Y						
412 N West		N	Y	1860	1860	Survey Response	G	G	G	GRR	Y						
420 North West Street		N	Y	1930	1930	Survey Response	G	G	G	GRR	Y						
602 N Stanton Street		N	Y	1996	1996	Survey Response	G	G	G	GRR	Y						
607 N Blackmore		N	Y	1854	1854	Survey Response	G	G	G	GRR	Y						
611 E Snyder		N	Y	1860	1860	Survey Response	G	G	G	GRR	Y						
615 N Stanton		N	Y	Unknown	Unknown	Visual Inspection	G	G	G	GRR	Y						
711 E Snyder St		N	Y	Unknown	Unknown	Survey Response	G	G	G	GRR	Y						

719 N Lee		N	Y	1984	1984	Survey Response	G	G	G	GRR	Y						
803 N West St		N	Y	1977	1977	Survey Response	G	G	G	GRR	Y						
811 E Webb St		N	Y	1968	1968	Survey Response	G	G	G	GRR	Y						
204 W McKimmy	20	N	Y	1950	1950	Survey Response	C	C	G	GRR	Y						
130 Stony Knoll	1	N	Y	1997	1997	Visual Inspection	C	C	L	L	Y						
211 N Stanton St	2	N	Y	1928	1928	Visual Inspection	C	C	L	L	Y						
219 Webb St	3	N	Y	Unknown	Unknown	Visual Inspection	C	C	L	L	Y						
303 E Snyder	4	N	Y	1890	1890	Visual Inspection	C	C	L	L	Y						
319 N Salisbury	5	N	Y	1930s	1930s	Visual Inspection	G	G	L	L	Y						
400 Primrose Ln	6	N	Y	Unknown	Unknown	Visual Inspection	C	C	L	L	Y						
403 Lee Street	7	N	Y	1900s	1900s	Visual Inspection	C	C	L	L	Y						
403 N Turner St	8	N	Y	1872	1872	Visual Inspection	C	C	L	L	Y						
505 N Stanton St		N	Y	1926	1926	Survey Response	L	L	L	L	Y						
604 E Snyder	10	N	Y	1920	1920	Visual Inspection	C	C	L	L	Y						
611 E Dawson St	11	N	Y	1959	1959	Visual Inspection	C	C	L	L	Y						
704 N Lee St	13	N	Y	1858	1858	Visual Inspection	G	G	L	L	Y						
719 N Stanton	14	N	Y	Unknown	Unknown	Visual Inspection	G	G	L	L	Y						
720 Blackmore	15	N	Y	1900	1900	Visual Inspection	G	G	L	L	Y						
619 N Blackmore	12	N	Y	1914	1914	Visual Inspection	C	C	L	L	Y						
101 Untersee Ct	16	N	Y	1993	1993	Survey Response	C	C	G	L	Y						
108 N East St	17	N	Y	1961	1961	Survey Response	C	C	G	L	Y						
111 W Kimmy St	18	N	Y	Unknown	Unknown	Survey Response	C	C	G	L	Y						
100 N West St		N	N	Unknown	Unknown	Survey Response	C	C	C	NL	N	4/1/2020	Y		2/10/2023	C	
100 Rt 75		N	Y	1993	1993	Survey Response	C	C	C	NL	N	N/R	N				
101 E Carnifix		N	Y	1996	1996	Survey Response	C	C	C	NL	N	N/R	N				
101 E Dawson		N	Y	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
101 Eply St		N	Y	2003	2003	Survey Response	C	C	C	NL	N	N/R	N				
101 N East St		N	Y	1994	1994	Survey Response	C	C	C	NL	N	N/R	N				
102 E Dawson Street		N	Y	1993	1993	Survey Response	C	C	C	NL	N	N/R	N				
102 Ina Dr		N	Y	1999	1999	Survey Response	C	C	C	NL	N	N/R	N				
102 W McKimmy St		N	Y	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R	N				
102 Untersee Ct		N	Y	1992	1992	Survey Response	C	C	C	NL	N	N/R	N				
103 Untersee Ct		N	Y	1979	1979	Survey Response	C	C	C	NL	N	N/R	N				
103 W McKimmy St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
103 E Eply		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
103 Ina Dr		N	Y	1995	1995	Survey Response	C	C	C	NL	N	N/R	N				
103 Norton St		N	Y	1985	1985	Survey Response	C	C	C	NL	N	N/R	N				
103 Rt 75		N	Y	1990	1990	Survey Response	C	C	C	NL	N	N/R	N				
104 E Carnifix St		N	Y	1910	1910	Survey Response	C	C	C	NL	N	N/R	N				
104 E McKimmy		N	Y	2000	2000	Survey Response	C	C	C	NL	N	N/R	N				
104 Ina Dr		N	Y	1993	1993	Survey Response	C	C	C	NL	N	N/R	N				
104 E Webb		N	Y	2003	2003	Visual Inspection	C	C	C	NL	N	N/R	N				
104 Untersee Ct		N	Y	1992	1992	Survey Response	C	C	C	NL	N	N/R	N				
10400 E Stanton Rd		N	Y	1980	1980	Survey Response	C	C	C	NL	N	N/R	N				
105 Stony Knoll		N	Y	1994	1994	Survey Response	C	C	C	NL	N	N/R	N				
105 Untersee Ct		N	Y	1986	1986	Survey Response	C	C	C	NL	N	N/R	N				
106 Untersee Ct		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
106 Stony Knoll		N	Y	1999	1999	Survey Response	C	C	C	NL	N	N/R	N				
107 IL RTE 75		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
107 Stony Knoll		N	Y	1994	1994	Survey Response	C	C	C	NL	N	N/R	N				
107 N Turner St		N	Y	1963	1963	Survey Response	C	C	C	NL	N	N/R	N				
108 Miller Ct		N	Y	1997	1997	Survey Response	C	C	C	NL	N	N/R	N				
108 Untersee Ct		N	Y	1979	1979	Survey Response	C	C	C	NL	N	N/R	N				
109 Miller Ct		N	Y	1995	1995	Survey Response	C	C	C	NL	N	N/R	N				
110 Miller Ct		N	Y	1996	1996	Survey Response	C	C	C	NL	N	N/R	N				
111 E Dawson		N	Y	1970	1970	Survey Response	C	C	C	NL	N	N/R	N				
111 E McKimmy St		N	Y	1957	1957	Survey Response	C	C	C	NL	N	N/R	N				
111 Miller Court		N	Y	1995	1995	Survey Response	C	C	C	NL	N	N/R	N				
111 North St		N	Y	1957	1957	Survey Response	C	C	C	NL	N	N/R	N				
111 Primrose		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R	N				
111 N Stanton		N	Y	1967	1967	Survey Response	C	C	C	NL	N	N/R	N				
112 E Carnifix St		N	Y	1890	1890	Survey Response	C	C	C	NL	N	N/R	N				
112 E Snyder		N	Y	1908	1908	Survey Response	C	C	C	NL	N	N/R	N				
112 N Stanton St		N	Y	1963	1963	Survey Response	C	C	C	NL	N	N/R	N				
112 Stony Knoll		N	Y	1998	1998	Survey Response	C	C	C	NL	N	N/R	N				

112 W Carnifix St		N	Y	1950	1950	Survey Response	C	C	C	NL	N	N/R					
112 W McKimmy		N	Y	1925	1925	Visual Inspection	C	C	C	NL	N	N/R					
113 Stony Knoll		N	Y	1995	1995	Survey Response	C	C	C	NL	N	N/R					
114 Stony Knoll		N	Y	1994	1994	Survey Response	C	C	C	NL	N	N/R					
116 S Klever Dr		N	Y	1993	1993	Survey Response	C	C	C	NL	N	N/R					
115 S Klever Dr		N	Y	1995	1995	Survey Response	C	C	C	NL	N	N/R					
117 Klever Dr		N	Y	1994	1994	Survey Response	C	C	C	NL	N	N/R					
118 Z Klever Dr		N	Y	1992	1992	Survey Response	C	C	C	NL	N	N/R					
119 N Lee St		N	Y	1970	1970	Survey Response	C	C	C	NL	N	N/R					
119 N Stanton St		N	Y	1962	1962	Survey Response	C	C	C	NL	N	N/R					
121 Ina Dr		N	Y	1995	1995	Survey Response	C	C	C	NL	N	N/R					
122 Ina Dr		N	Y	1998	1998	Survey Response	C	C	C	NL	N	N/R					
123 Ina Dr		N	Y	1996	1996	Survey Response	C	C	C	NL	N	N/R					
124 Ina Dr		N	Y	1996	1996	Survey Response	C	C	C	NL	N	N/R					
125 Stony Knoll		N	Y	1996	1996	Survey Response	C	C	C	NL	N	N/R					
126 Stony Knoll		N	Y	1999	1999	Survey Response	C	C	C	NL	N	N/R					
131 S Klever Dr		N	Y	2000	2000	Survey Response	C	C	C	NL	N	N/R					
132 S Klever		N	Y	2000	2000	Survey Response	C	C	C	NL	N	N/R					
201 E Eply		N	Y	2002	2002	Survey Response	C	C	C	NL	N	N/R					
201 N Beman		N	Y	2008	2008	Survey Response	C	C	C	NL	N	N/R					
202 E Carnifix		N	Y	1987	1987	Survey Response	C	C	C	NL	N	N/R					
203 E Eply St		N	Y	2001	2001	Survey Response	C	C	C	NL	N	N/R					
203 E McKimmy St		N	Y	1979	1979	Survey Response	C	C	C	NL	N	N/R					
203 E Snyder		N	Y	1970	1970	Survey Response	C	C	C	NL	N	N/R					
204 E Snyder		N	Y	1970	1970	Survey Response	C	C	C	NL	N	N/R					
204 N Turner St		N	Y	1920	1920	Survey Response	C	C	C	NL	N	N/R					
205 Eply St		N	Y	2003	2003	Survey Response	C	C	C	NL	N	N/R					
206 E Snyder St		N	Y	1995	1995	Survey Response	C	C	C	NL	N	N/R					
211 E Webb St		N	Y	1978	1978	Survey Response	C	C	C	NL	N	N/R					
212 E Dawson		N	Y	1857	1857	Survey Response	C	C	C	NL	N	N/R					
212 N Salisbury		N	Y	1952	1952	Survey Response	C	C	C	NL	N	N/R					
212 W McKimmy		N	Y	1978	1978	Survey Response	C	C	C	NL	N	N/R					
219 N Stanton		N	Y	1890	1890	Survey Response	C	C	C	NL	N	N/R					
219 N Turner St		N	Y	1940	1940	Survey Response	C	C	C	NL	N	N/R					
220 Marsh St		N	Y	1978	1978	Survey Response	C	C	C	NL	N	N/R					
220 N Turner		N	Y	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R					
220 N Stanton		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
220 N Salisbury		N	Y	1917	1917	Survey Response	C	C	C	NL	N	N/R					
221 N Marsh		N	Y	1978	1978	Survey Response	C	C	C	NL	N	N/R					
245 W Wright		N	Y	1994	1994	Survey Response	C	C	C	NL	N	N/R					
244 N Wright St		N	Y	1991	1991	Survey Response	C	C	C	NL	N	N/R					
303 Beman St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
303 E Carnifix St		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
303 N Stanton		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
304 N Stanton St		N	Y	1890	1890	Survey Response	C	C	C	NL	N	N/R					
304 E Carnifix		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
304 N Turner St		N	Y	1930	1930	Survey Response	C	C	C	NL	N	N/R					
310 N Lee St		N	Y	1982	1982	Survey Response	C	C	C	NL	N	N/R					
311 N Blackmore St		N	Y	1984	1984	Survey Response	C	C	C	NL	N	N/R					
311 N Stanton St		N	Y	1905	1905	Survey Response	C	C	C	NL	N	N/R					
311 N Salisbury		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
312 E Webb St		N	Y	1950	1950	Survey Response	C	C	C	NL	N	N/R					
312 N Stanton		N	Y	1890	1890	Survey Response	C	C	C	NL	N	N/R					
312 N Marsh St		N	Y	1920	1920	Survey Response	C	C	C	NL	N	N/R					
319 N Turner		N	Y	1989	1989	Survey Response	C	C	C	NL	N	N/R					
319 N Beman St		N	Y	1988	1988	Survey Response	C	C	C	NL	N	N/R					
319 N Wright St		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
320 N Lee Street		N	Y	1904	1904	Survey Response	C	C	C	NL	N	N/R					
320 N Stanton St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
401 Primrose		N	Y	1972	1972	Survey Response	C	C	C	NL	N	N/R					
403 E Webb		N	Y	1919	1919	Survey Response	C	C	C	NL	N	N/R					
404 N Stanton St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
404 N West St		N	Y	1864	1864	Survey Response	C	C	C	NL	N	N/R					
405 Primrose Ln		N	Y	1979	1979	Survey Response	C	C	C	NL	N	N/R					
407 N Turner St		N	Y	1995	1995	Survey Response	C	C	C	NL	N	N/R					

408 N Stanton		N	Y	1919	1919	Visual Inspection	C	C	C	NL	N	N/R					
408 N Salisbury		N	Y	1920	1920	Survey Response	C	C	C	NL	N	N/R					
409 Primrose Ln		N	Y	1972	1972	Survey Response	C	C	C	NL	N	N/R					
411 N West St		N	Y	1968	1968	Survey Response	C	C	C	NL	N	N/R					
412 N Stanton		N	Y	1950	1950	Survey Response	C	C	C	NL	N	N/R					
412 Carnifix St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
412 S Salisbury St		N	Y	1936	1936	Survey Response	C	C	C	NL	N	N/R					
413 Primrose Ln		N	Y	1974	1974	Survey Response	C	C	C	NL	N	N/R					
415 N Blackmore		N	Y	1978	1978	Survey Response	C	C	C	NL	N	N/R					
415 N Turner		N	Y	1940	1940	Survey Response	C	C	C	NL	N	N/R					
419 N Lee		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
419 N West St		N	Y	2021	2021	Survey Response	C	C	C	NL	N	N/R					
419 Turner St		N	Y	1940	1940	Survey Response	C	C	C	NL	N	N/R					
419 N Salisbury		N	Y	1920	1920	Survey Response	C	C	C	NL	N	N/R					
419 Webb St		N	Y	1950	1950	Survey Response	C	C	C	NL	N	N/R					
420 N Lee		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
420 E Webb		N	Y	1963	1963	Survey Response	C	C	C	NL	N	N/R					
420 N Stanton		N	Y	1963	1963	Visual Inspection	C	C	C	NL	N	N/R					
420 N Turner		N	Y	1860	1860	Survey Response	C	C	C	NL	N	N/R					
420 Primrose Ln		N	Y	1990	1990	Survey Response	C	C	C	NL	N	N/R					
420 Rt 75		N	Y	1858	1858	Survey Response	C	C	C	NL	N	N/R					
421 Primrose Ln		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
425 Primrose Ln		N	Y	1978	1978	Survey Response	C	C	C	NL	N	N/R					
502 E Webb St		N	Y	1993	1993	Survey Response	C	C	C	NL	N	N/R					
503 N Salisbury		N	Y	1920	1920	Survey Response	C	C	C	NL	N	N/R					
503 N Lee St		N	Y	1993	1993	Survey Response	C	C	C	NL	N	N/R					
504 N Stanton St		N	Y	1926	1926	Survey Response	C	C	C	NL	N	N/R					
504 IL RTE 75		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
504 Turner St		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
507 North Stanton Street		N	Y	1960	1960	Survey Response	C	C	C	NL	N	N/R					
508 N West St		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
509 N Stanton St		N	Y	1895	1895	Survey Response	C	C	C	NL	N	N/R					
509 1/2 N Stanton St		N	Y	1885	1885	Survey Response	C	C	C	NL	N	N/R					
511 N Salisbury		N	Y	1930	1930	Visual Inspection	C	C	C	NL	N	N/R					
511 N Stanton St		N	Y	1897	1897	Survey Response	C	C	C	NL	N	N/R					
511 N Turner St		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
512 N Stanton		N	Y	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R					
512 1/2 N Stanton		N	Y	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R					
512 N Salisbury		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
512 E Eply St		N	Y	1908	1908	Survey Response	C	C	C	NL	N	N/R					
512 Turner St		N	Y	1920	1920	Survey Response	C	C	C	NL	N	N/R					
515 N Stanton St	9	N	Y	Unknown	Unknown	Visual Inspection	C	C	L	NL	N	N/R					
513 S Salisbury		N	Y	1988	1988	Survey Response	C	C	C	NL	N	N/R					
515 N Turner		N	Y	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R					
516 N Stanton St		N	Y	1904	1904	Survey Response	C	C	C	NL	N	N/R					
519 N West		N	Y	1880	1880	Survey Response	C	C	C	NL	N	N/R					
520 E Dawson		N	Y	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R					
520 Davis St		N	Y	1898	1898	Survey Response	C	C	C	NL	N	N/R					
523 Stanton St		N	Y	1965	1965	Survey Response	C	C	C	NL	N	N/R					
524 N Stanton St		N	Y	1900	1900	Visual Inspection	C	C	C	NL	N	N/R					
603 N Stanton		N	Y	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R					
604 E Eply		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
604 E Webb St		N	Y	1965	1965	Survey Response	C	C	C	NL	N	N/R					
604 N Blackmore		N	Y	1871	1871	Visual Inspection	C	C	C	NL	N	N/R					
604 N West St		N	Y	1945	1945	Survey Response	C	C	C	NL	N	N/R					
608 N West		N	Y	1945	1945	Survey Response	C	C	C	NL	N	N/R					
608 N Turner St		N	Y	1899	1899	Survey Response	C	C	C	NL	N	N/R					
609 N Davis St		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R					
609 N West St		N	Y	1860	1860	Survey Response	C	C	C	NL	N	N/R					
611 Blackmore St		N	Y	1930	1930	Survey Response	C	C	C	NL	N	N/R					
612 E Dawson St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
612 N Blackmore		N	Y	2006	2006	Survey Response	C	C	C	NL	N	N/R					
612 Eply St		N	Y	1950	1950	Survey Response	C	C	C	NL	N	N/R					
612 N West St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R					
614 E Webb St		N	Y	1960	1960	Survey Response	C	C	C	NL	N	N/R					

615 1/2 N Turner		N	Y	1880s	1880s	Survey Response	C	C	C	NL	N	N/R				
615 N Turner		N	Y	1880s	1880s	Survey Response	C	C	C	NL	N	N/R				
615 E Webb St		N	Y	1969	1969	Survey Response	C	C	C	NL	N	N/R				
615 Eply St		N	Y	1890	1890	Survey Response	C	C	C	NL	N	N/R				
616 N West		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R				
616 N Davis St		N	Y	1958	1958	Survey Response	C	C	C	NL	N	N/R				
619 N Turner St		N	Y	1926	1926	Survey Response	C	C	C	NL	N	N/R				
704 N Turner		N	Y	1908	1908	Survey Response	C	C	C	NL	N	N/R				
704 N West		N	Y	1860	1860	Survey Response	C	C	C	NL	N	N/R				
704 E Snyder		N	Y	1976	1976	Survey Response	C	C	C	NL	N	N/R				
704 N Davis St		N	Y	1954	1954	Survey Response	C	C	C	NL	N	N/R				
707 E Eply St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R				
707 E Webb St		N	Y	1961	1961	Survey Response	C	C	C	NL	N	N/R				
708 N Stanton St		N	Y	1982	1982	Visual Inspection	C	C	C	NL	N	N/R				
708 N Turner St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R				
709 N Turner St		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R				
710 N Lee		N	Y	1986	1986	Survey Response	C	C	C	NL	N	N/R				
711 N Blackmore		N	Y	1963	1963	Survey Response	C	C	C	NL	N	N/R				
711 East Webb Street		N	Y	1960	1960	Survey Response	C	C	C	NL	N	N/R				
712 Eply St		N	Y	1965	1965	Survey Response	C	C	C	NL	N	N/R				
712 N Davis St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R				
712 N Stanton St		N	Y	1924	1924	Survey Response	C	C	C	NL	N	N/R				
712 N West St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R				
715 N Lee		N	Y	1930	1930	Survey Response	C	C	C	NL	N	N/R				
716 N Turner		N	Y	1965	1965	Visual Inspection	C	C	C	NL	N	N/R				
719 N West St		N	Y	1987	1987	Survey Response	C	C	C	NL	N	N/R				
720 N Stanton St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R				
720 N Davis St		N	Y	1956	1956	Survey Response	C	C	C	NL	N	N/R				
720 N Lee St		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R				
720 N West St		N	Y	1903	1903	Survey Response	C	C	C	NL	N	N/R				
721 N Blackmore		N	Y	1997	1997	Survey Response	C	C	C	NL	N	N/R				
725 N Blackmore St		N	Y	1981	1981	Survey Response	C	C	C	NL	N	N/R				
804 E Webb St		N	Y	1970	1970	Survey Response	C	C	C	NL	N	N/R				
804 N West		N	Y	Unknown	Unknown	Survey Response	C	C	C	NL	N	N/R				
902 East Snyder Street		N	Y	1970	1970	Survey Response	C	C	C	NL	N	N/R				
904 E Webb St		N	Y	1949	1949	Survey Response	C	C	C	NL	N	N/R				
904 E Snyder		N	Y	1930s	1930s	Survey Response	C	C	C	NL	N	N/R				
911 E Webb St		N	Y	1900	1900	Survey Response	C	C	C	NL	N	N/R				
7991 N Davis Rd		N	Y	1978	1978	Survey Response	C	C	C	NL	N	N/R				
312 N Turner		N	Y	1900	1900	Visual Inspection	C	C	C	NL	N	N/R				
10584 IL RT 75 East		N	Y	1997	1997	Survey Response	C	C	C	NL	N	N/R				
107 Untersee Ct		N	Y	1977	1977	Survey Response	C	C	C	NL	N	N/R				
511 1/2 N Stanton		N	Y	Unknown	Unknown	Visual Inspection	C	C	C	NL	N	N/R				
10500 N Stanton St		N	Y	1969	1969	Survey Response	P	P	P	NL	N	N/R				
10580 E Snyder St		N	Y	1993	1993	Survey Response	P	P	P	NL	N	N/R				
129 Stony Knolls		N	Y	1994	1994	Survey Response	P	P	P	NL	N	N/R				
204 N Lee St		N	Y	1898	1898	Survey Response	P	P	P	NL	N	N/R				
304 N Lee		N	Y	1900s	1900s	Visual Inspection	P	P	P	NL	N	N/R				
304 Rt 75		N	Y	1930	1930	Survey Response	P	P	P	NL	N	N/R				
404 E Dawson St		N	Y	1910	1910	Survey Response	P	P	P	NL	N	N/R				
411 N Stanton St		N	Y	Unknown	Unknown	Survey Response	P	P	P	NL	N	N/R				
412 Primrose Ln		N	Y	1974	1974	Survey Response	P	P	P	NL	N	N/R				
604 N Turner		N	Y	Unknown	Unknown	Survey Response	P	P	P	NL	N	N/R				
620 N Stanton St		N	Y	1880	1880	Survey Response	P	P	P	NL	N	N/R				
620 N East St		N	Y	1863	1863	Survey Response	P	P	P	NL	N	N/R				
712 E Webb		N	Y	1974	1974	Survey Response	P	P	P	NL	N	N/R				
721 N Stanton		N	Y	Unknown	Unknown	Survey Response	P	P	P	NL	N	N/R				
802 IL RTE 75		N	Y	2010	2010	Survey Response	P	P	P	NL	N	N/R				
815 E Webb St		N	Y	1987	1987	Survey Response	P	P	P	NL	N	N/R				
8509 N Davis Rd		N	Y	1974	1974	Survey Response	P	P	P	NL	N	N/R				
520 N Stanton St		N	Y				U	U	U							